

## News



MED17 CHECKSUM FIXED

### Small update for checksum fix

September 14, 2023

Update checksum for mcu TC1766 TC1793 TC1797 TC1724F TC1767  
foxFlash is now able to perform the following operations:

software calculate checksum

On the following ECU reference:

Audi Bosch MED17.5 TC1766

Audi Bosch MED17.5.5 TC1766

Audi Bosch MED17.5.20 TC1766

Audi Temic VL381F TC1766

BMW Bosch EDC17C76 TC1793

Honda Bosch EDC17CP50 TC1797

Hyundai Bosch ME17.9.21.1 TC1724F

Jaguar Bosch MED17.9.7 TC1797

KIA Bosch ME17.9.21.1 TC1724F

Land Rover Bosch MED17.9.7 TC1797

Mercedes Bosch EDC17CP01 TC1796

Mercedes Bosch MED17.7.7 TC1793

Mercedes Bosch MED17.7.7 TC1797

Renault Bosch EDC17CP58 TC1767

Seat Bosch MED17.5 TC1766

Seat Bosch MED17.5.5 TC1766

# Foxflash.co.uk

Seat Bosch MED17.5.20 TC1766  
Skoda Bosch MED17.5 TC1766  
Skoda Bosch MED17.5 TC1766  
Skoda Bosch MED17.5.5 TC1766  
Skoda Bosch MED17.5.20 TC1766  
Toyota Bosch EDC17C60 TC1793  
Volkswagen (VW) Bosch ME17.5.6 TC1766  
Volkswagen (VW) Bosch MED17.5 TC1766  
Volkswagen (VW) Bosch MED17.5.5 TC1766  
Volkswagen (VW) Bosch MED17.5.20 TC1766

Update method: Click the download button in foxFlash manager till all file download complete

Update method: Click the download button in foxFlash manager till all file download complete